

#### Update descriptions:

1. Update 7/8/08 - An error in hydrologic unit coding was found in the Sandusky subbasin (04100011). Fixes have been applied to Sandusky.zip and oh\_huc12.zip.
2. Update 10/13/08 - The HU\_10\_name for HUC12 "050302020802" has been corrected from "Pond Creek-Ohio River" to "Little Sandy Creek-Ohio River". oh\_huc12.zip and OhioRiv3.zip have been corrected.
3. Update 1/8/09 - HU\_12\_name for HUC12 "041100010204" made consistent for 2 separate polygons that together make up the hydrologic unit. oh\_huc12.zip and BlackRoc.zip have been corrected.
4. Update 3/9/09 - Duplicate HU\_12\_name "Upper Rocky Fork" for HUC12 "050400020203" and "050400020204" changed to "Headwaters Rocky Fork" and "Outlet Rocky Fork", respectively.
5. Update 6/11/09 - HU\_10\_name for HUC12 "050902021305" corrected from "Shayler Run-East Fork Little Miami River" to "Stonelick Creek-East Fork Little Miami River".
6. Update 8/27/09 - Huc12 downstream codes were added, the data now contain complete 8-digit subbasins rather than stopping at the Ohio State Line, and one huc12 coding switch was made, namely, 050902010303 was switched with 050902010304.
7. Update 9/24/09 - HU\_12\_name for "050901010403" changed from "Meadow Run-Little Raccoon Creek" to "Mulga Run-Little Raccoon Creek". Narrative descriptions corrected for "050901010401" and "050901010403" to include Meadow Run in the former HUC\_12 and not in the latter.
8. Update 2/26/10 - Spelling and name consistency corrections were made to HU\_10\_Name/ HU\_12\_Name attributes in files RiverRaisin.zip, Black\_Rocky.zip, Shenango.zip, UpperOhio\_Wheeling.zip, LowerScioto.zip and OH\_huc12.zip.
9. Update 4/14/11 – Correction to HU\_10\_Name for “0410000702” and spelling corrections to HU\_12\_Name for “041000100601” and “050400040201”. Corrections applied to Auglaize.zip, Cedar-Portage.zip, Muskingum.zip and OH\_Huc12.zip.